1. Incident Name:		2. Operation	al Pei	riod: (D	ASSIGNMENT	ASSIGNMENT LIST			
Gold King Mine Spill (R6)		From: 08 / 18 / 2015 0700 To: 08 / 19 /2015 0700					ICS 204 - EPA		
3. Branch: 4. Division/Group/Staging:									
R6 New Mexico	PWS Assessment and Sampling								
5. Operations Personnel:									
ICS Position	Name			Affiliation		Contact # (s)			
Operations Section Chief:	Jon Rinehart			R6 OSC		214 – 789 - 1713			
Branch Director:	Jon Rinehart			R6 OSC		214 – 789 - 1713			
Division/Group Supervisor/STAM:	Mark McCasland			R6 Water Quality 8		817-706-83	817-706-8384		
6. Resources Assigned:				"X" indica	ates 204a	attachment w	vith additional instructions		
Strike Team/Task Force/ Resource Identifier	Leader		Cor	ntact Info. #	# of Persons	Rep	orting Info/Notes/Remarks		
PWS Assessment Team	Kurt Limesand (EPA) 816 CBI/Ex. 4			401-9863	2	Assess 5 PWS Treatment Plants for appropriate sample locations			
PWS Sampling Team 1	Mark McCasland (EPA)	_		706-8384	4		ples of PWS treated to distribution to		
Morningstar Pump Installation Team	CBI	<i>(</i>	\ .	4	2	of pump co	nstallation and operation nnecting Morningstar em to Farmington Water		
7. Work Assignments:									
8. Special Instructions:	COMP.								
For claims inquiries: (To MEDIA Inquiries, call 970 In the event of an emerg)-812-3351	elow-referenc	ced n	umbers and	notify or	ne of the Depu	uty RICs ASAP		
9. Communications (ra	dio and/or phone conta	act numbers	need	led for this	assignn	nent):			
Name/Function Radio: Freq./System/Channel				Phone			Cell/Pager		
				of emergency contact 911					
OSC Roberto Bernier 214-212-4304									
	CBI/Ex	. 4							
10. Prepared by: (RESL) (Date / 11. Reviewed by: (PSC) (Date Time)						12. Reviewed by: (OPS) (Date / Time)			
CBI/Ex. 4						•			
ASSIGNMENT LIST						ICS 204 – EPA (Rev 02/10)			